LENGTH AND SPACING TABLE											
APPROACH		LENGTH	CHANNELI	ZING DEVICE	SPACING	CONCRETE					
SPEED	"" MINIMUM TAPER	OF BUFFER	**TAPER	BUFFER	WORK	BARRIER					
*MILES	LENGTH IN FEET	SPACE IN	AREA	SPACE	SPACE	FLARE					
PER HOUR		FEET	SPACING IN FEET		RATE						
25	Shifting taper formula:	155	25	50	50	1:8					
30	$L = \frac{WS^2}{120}$ for speeds of 40 mph or less	200	30	60	60	I <b>:</b> 8					
35	$L = \frac{WxS}{2}$ for speeds of 45 mph or greater	250	35	70	70	1:9					
40	Where:	305	40	80	80	1:10					
45	L= Minimum length of taper W= Width of offset in feet	360	45	90	90	1:12					
50	S= Numerical value of posted speed limit or 85 percentile speed prior to work in miles per hour	425	50	100	100	1:14					
55		495	55	110	110	1:16					

\* Speed is based on the regulatory posted speed and not the advisory speed. \*\* Lengthen taper as needed to provide minimum of three channelizing devices

in taper at required spacing.

SIGN SPACING TABLE							
	DIST	DISTANCE BETWEEN					
ROAD TYPE	SIC	SIGNS IN FEET					
	Α	В	С				
Urban 40 mph and less	100	100	100				
Urban 45 mph and greater	350	350	350				
Rural	500	500	500				
Expressway/Freeway	1000	1500	2640				

	are chown for	one direction of travel only.	
Δ٠	dovices similar	to those denicted for the	

STATE

PROJECT

Signs are shown for Place devices similar to those aepictea for the opposite direction of travel.

REG

- 2. Final location and spacing of signs and devices may be changed to fit field conditions as approved
- 3. Place the barrier according to the Roadside Design Guide by the American Association of State Highway and Transportation Officials (AASHTO). Terminate barrier ends outside the clear zone or protect the ends of the barrier with a crash cushion.
- 4. Refer to Special Contract Requirements, Section 156, for
- 5. Install temporary pavement markings if roadway surface is paved. Remove conflicting pavement markings.

NO SCALE

REVISED: 06/2004

- 6. If closure is completely within the project limits, eliminate the 'END ROAD WORK' sign (G20-2).
- 7. Install 'PASS WITH CARE' signs (R4-2) at ends of no-passing zones if directed by CO.
- 8. Omit the WI4-3 sign if already within a no-passing zone.
- 9. Do not allow equipment, materials, or vehicles to be parked or stored in the buffer space.

DETAIL

C635-12

